MALFUNCTION INDICATOR LAMP (MIL) ILLUMINATED WITH MULTIPLE DIAGNOSTIC TROUBLE CODES (DTCS) P035X AND NO DRIVEABILITY SYMPTOMS—4.6L 3V ENGINE

TSB 04-26-22

FORD:

2005 Mustang

ISSUE

Some 2005 Mustang vehicles equipped with a 4.6L 3-valve engine, may exhibit the MIL illuminated with multiple ignition coil related DTCs (P035X) and no driveability symptoms. The DTCs are typically set during deceleration.

ACTION

Do not replace ignition components for this condition. Reprogram the powertrain control module (PCM) to the latest calibration using WDS release B34.10, or B35.1 and higher. Calibration files may also be obtained at www.motorcraft.com.

NOTE

THIS NEW CALIBRATION IS NOT INCLUDED IN THE B35 CD.

WARRANTY STATUS: Eligible Under Provisions Of

New Vehicle Limited Warranty Coverage And Emissions Warranty

Coverage

OPERATION DESCRIPTION TIME
042622A 2005 Mustang 4.6L 3V: 0.4 Hr.

Check Diagnostic Trouble Codes And Reprogram Powertrain Control Module

DEALER CODING

BASIC PART NO. CODE
RECALEM 04

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supercede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.