

**EXHAUST VIBRATION AT 850 RPM—4.0L ENGINE  
AND AUTOMATIC TRANSMISSION**

**TSB 05-8-6**

**FORD:**

2005 Mustang

**ISSUE**

Some 2005 Mustang vehicles equipped with a 4.0L engine and automatic transmission, may exhibit an exhaust vibration or resonance at approximately 850 RPM.

**ACTION**

Install a damper kit to counter the effects of the vibrating exhaust. Refer to the installation instruction sheet included in damper kit.

**WARRANTY STATUS:** Eligible Under Provisions Of  
New Vehicle Limited  
Warranty Coverage

<b>OPERATION</b>	<b>DESCRIPTION</b>	<b>TIME</b>
050806A	2005 Mustang 4.0L Install Damper Kit (Do Not Use With 5200A)	0.4 Hr.

**DEALER CODING**

BASIC PART NO.  
5F240

CONDITION  
CODE  
42

<b>PART NUMBER</b>	<b>PART NAME</b>
5R3Z-5F240-A	Damper Kit

**NOTE:** The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supercede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.