

# LUGGAGE COMPARTMENT LID SOLENOID STUCK OPEN

TSB 10-5-9

**FORD:**

2006-2010 Crown Victoria, Focus, Fusion, Mustang, Taurus

**LINCOLN:**

2006 Zephyr

2007-2010 MKZ

2009 MKS

**MERCURY:**

2006-2009 Sable

2006-2010 Grand Marquis, Milan

This article supersedes TSB **09-14-8** to update the Part List.

**ISSUE**

Some 2006-2010 vehicles may exhibit an inoperative luggage compartment lid solenoid. The solenoid may be stuck in the open position, preventing the luggage compartment lid from latching.

**ACTION**

Follow the Service Procedure steps to correct the condition.

**SERVICE PROCEDURE**

1. With the luggage compartment lid open and the key in the accessory position, cycle the luggage compartment latch with the luggage compartment release button inside the passenger compartment. After hearing the latch actuate, attempt to close the luggage compartment lid.
  - a. If the lid closes no further action is required.
  - b. If the lid does not close go to Step 2.
2. Using the Work Shop Manual (WSM), Section 501-14, remove luggage compartment lid latch trim.
3. Check to ensure the electrical connector is fully seated into the luggage compartment lid release solenoid. Inspect the release T shaped interior handle for correct routing and free movement.
4. Cycle the luggage compartment latch per Step 1. If the lid still does not close, replace the latch assembly.

PART NUMBER	PART NAME
8G1Z-5443200-A	Lock Assembly (MKS/Taurus/Sable)
6E5Z-5443200-D	Lock Assembly (2006-2007 Fusion/Milan/Zephyr/MKZ built to 9/2006)
7E5Z-5443200-B	Lock Assembly (2007-2009 Fusion/Milan/MKZ built to 2/2009 )
AE5Z-5443200-A	Lock Assembly (2010 Fusion/Milan/MKZ )
6R3Z-6343200-B	Lock Assembly (2006-2007 Mustang)
8R3Z-5443200-A	Lock Assembly (2008-2010 Mustang)
7W7Z-5443200-A	Lock Assembly (Crown Victoria/Grand Marquis)
AS4Z-5443200-A	Lock Assembly (Focus)

**WARRANTY STATUS:** Eligible Under Provisions Of New Vehicle Limited Warranty Coverage  
**IMPORTANT:** Warranty coverage limits/policies are not altered by a TSB. Warranty coverage limits are determined by the identified causal part.

OPERATION	DESCRIPTION	TIME
100509A	2009 MKS, 2006-2010 Fusion, Milan, Mustang, 2006 Zephyr 2007-2010 MKZ: Includes Time To Diagnose and Replace The Latch Assembly (Do Not Use With Any Other Labor Operation)	0.4 Hr.

**NOTE:** The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.

## TSB 10-5-9 (Continued)

- 100509A 2006-2010 Crown Victoria, 0.4 Hr.  
Grand Marquis, Taurus,  
2008-2009 Sable: Includes  
Time To Diagnose and  
Replace The Latch  
Assembly (Do Not Use  
With Any Other Labor  
Operation)
- 100509A 2006-2010 Focus: Includes 0.6 Hr.  
Time To Diagnose and  
Replace The Latch  
Assembly (Do Not Use  
With Any Other Labor  
Operation)

### DEALER CODING

BASIC PART NO.  
5443200

CONDITION  
CODE  
41