

## **Installation Instructions: Door Lock Actuator**

(performed on a 1989 Mustang 5.0 LX Coupe)



*Latemodel Restoration Supply - 1979-Preseny Mustang parts*

**Symptoms that point to the need to replace the power door lock actuators are when they fail intermittently (especially in cold weather), or if they fail completely. In this case, the actuators were known to be at fault as the passenger side worked consistently and the driver side failed intermittently.**

**Since I had the tools already out, I replaced both sides at the same time to avoid any future failures.**




**The following steps to remove the power door lock actuators were based on my 1989 Mustang 5.0 LX Coupe. It was designed to serve as a visual reference for readers to see how I performed the replacement.**




























**This is the heavy duty riveter used with a 7/32" (6.0mm) nose piece for the inserted rivet's shaft. A simple operation: squeeze the handles toward each other.**











© 2002-04, Gerry Tseng

