

**Installation Instructions: Door Panel Clips**  
(performed on a 1989 Mustang 5.0 LX Coupe)




*Latemodel Restoration Supply - 1979-2001 Mustang parts*

Door panel clips get torn up pretty badly if the panel was ever taken off after Ford originally put them on. This results in some annoying squeaks and rattles from the panel not being able to snug closely to the door. If you ever have to take the panel off for some reason (i.e. speaker install, door lock actuator replacement, etc), then its worth getting new door panel clips while you're at it.









Look closely and notice that this door panel was missing 2 clips.

Here are the old door panel clips. Most do not have much gripping ability left.

These new ones ensure the door panel attaches snug to the door for less rattle noise.





Here's a shot of the door panel with 12 new black clips along the edges.



© 2002-04, Gerry Tseng

